



### Report of Fire Extinguisher Inspection

Your Fire Protection Specialist!			Date	05/15/2008
Building Name	Customer Example			
Contact Name	John Doe			
Address	1234 Practice Lane			
City	Atlanta			
State	GA	Zip	30305	
Ext Inspected	60			

#### Device Testing

Size	Type	Location	Floor	Last Service Date	Future Service Date	Inspected	Tagged	Remarks/Comments
10 lb	ABC	Admin. Hallway #1	1st	2004	Hydro/2010	X	X	
10 lb	ABC	Admin. Hallway #4	1st	2004	Hydro/2010	X	X	
10 lb	ABC	File Room #2	1st	2004	Hydro/2010	X	X	
15.5 lb	Halotron	Computer Room #46	1st	2000	6yr/2006	X	X	Needs 6 Year Maintenance
10 lb	ABC	Break Room #3	1st	2000	6yr/2006	X	X	Needs 6 Year Maintenance
10 lb	ABC	Warehouse #5	1st	2004	Hydro/2010	X	X	
10 lb	ABC	Dock Area #8	1st	2005	Hydro/2011	X	X	
10 lb	ABC	Warehouse #6	1st	2004	Hydro/2010	X	X	
10 lb	ABC	Warehouse #10	1st	2004	Hydro/2010	X	X	
10 lb	ABC	Process Area #24	1st	2004	Hydro/2010	X	X	
5 lb	ABC	On Roller Cart	1st	2000	6yr/2006	X	X	Needs 6 Year Maintenance
10 lb	ABC	On Column Process Area	1st	2007	6yr/2013	X	X	
10 lb	ABC	Across On Other Column	1st	2007	6yr/2013	X	X	
20 lb	ABC	Process Area	1st	2006	6yr/2012	X	X	
10 lb	ABC	Hallway #12	1st	2004	Hydro/2012	X	X	
20 lb	ABC	On Column South of Process Area	1st	2006	6yr/2012	X	X	
10 lb	ABC	In Stairwell	1st	2000	6yr/2006	X	X	Needs 6 Year Maintenance
10 lb	ABC	Process Area #1	1st	2000	6yr/2006	X	X	Needs 6 Year Maintenance
10 lb	ABC	Utility Room #21	1st	2003	Hydro/2009	X	X	
2.5 lb	ABC	On Fork Lift	1st	2006	6yr/2012	X	X	
10 lb	ABC	Screening Room	1st	2006	6yr/2012	X	X	
10 lb	ABC	Next to Screening Room #43	1st	2004	Hydro/2010	X	X	
20 lb	ABC	Out Back by the Gas Tank	NA	2000	6yr/2006	X	X	Needs 6 Year Maintenance
5 lb	ABC	In Track Car Mover	1st	2006	6yr/2012	X	X	
10 lb	ABC	Rail Car Unloading #41	1st	2004	Hydro/2010	X	X	
10 lb	ABC	Rail Car Loading #39	1st	2004	Hydro/2010	X	X	
10 lb	ABC	Rail Car- Upstairs #38	1st	2004	Hydro/2010	X	X	
10 lb	ABC	Rail Car- Other Side #40	1st	2000	6yr/2006	X	X	Needs 6 Year Maintenance
10 lb	ABC	Rail Car- Down Stairs #40	1st	2005	Hydro/2011	X	X	
10 lb	ABC	Lab Hallway #9	1st	2004	Hydro/2010	X	X	
10 lb	CO2	Lab Room	1st	2006	Hydro/2011	X	X	
10 lb	ABC	West Wall- Outside	NA	2006	6yr/2012	X	X	
10 lb	ABC	Break Room	1st	2006	6yr/2012	X	X	
10 lb	ABC	Break Room	1st	2000	6yr/2006	X	X	Needs 6 Year Maintenance
10 lb	ABC	SVB Station #20	1st	2004	Hydro/2010	X	X	
10 lb	ABC	MCC Upstairs Hallway #14	1st	2004	Hydro/2010	X	X	
10 lb	ABC	B-4 Process Area #29	3rd	2000	6yr/2006	X	X	Needs 6 Year Maintenance
10 lb	ABC	A-4 Process Area #30	3rd	2004	Hydro/2010	X	X	
20 lb	ABC	Out of Elevator	2nd	2006	6yr/2012	X	X	
10 lb	ABC	In Maintenance Room	2nd	2000	6yr/2006	X	X	Needs 6 Year Maintenance
10 lb	ABC	In Maintenance Room	2nd	2007	6yr/2013	X	X	
10 lb	ABC	Small Room by Maintenance	2nd	2007	6yr/2013	X	X	
10 lb	CO2	MCC Room #19	2nd	2006	Hydro/2011	X	X	
10 lb	CO2	MCC Room #19	2nd	2006	Hydro/2011	X	X	